

## *Hubbardston DPW Bi-Weekly Log*

Aug.29, 2020 – Sept.12, 2020

**Mon.Aug.31, 2020**

- 4:45 AM Dispatch called to remove a tree on Burnshirt Rd.
- Continue to add hardpack long the edge of the new pavement on Hale Rd. Ext.
- Continue sweeping in Dogwood North, and Geordie Ln.
- Continue to Brush mow New Templeton Rd. and Hale Rd.
- Patching Thompson Rd. per resident request
- Patched Dogwood south per resident request
- Mowed the Cemeteries

**Tues.Sept.1, 2020**

- Continue to Brush mow Hale Rd.
- Mowed the Cemeteries
- Continue Sweeping on Laurel St. and New Templeton Rd.
- Fixed watering system on the Sweeper
- Continue patching Thompson Rd. per resident request
- Patched Upper Intervale and per resident request
- Continue to add hardpack long the edge of the new pavement on Hale Rd. Ext
- Installed the EGR valve on car#2 FD pickup

**Wed.Sept.2, 2020**

- Opened up drains around town
- Continue to Brush mow Hale Rd. and started Healdville Rd.
- Installing body repair panels on the 94 GMC pickup
- Picked up parts at Madigan's for the 04 Mack
- Removed a dead animal on Williamsville Rd.
- Picked up barriers at the Rt.62 culverts

**Thurs.Sept.3, 2020**

- Hot patched Ragged Hill Rd., New Templeton Rd., parts of Main St.
- Worked on car#1 PD

**Mon.Sept.7, 2020**

- Labor Day

**Tues.Sept.8, 2020**

- Started to put down the restorative maintenance application down on New Templeton Rd. and Hale Rd.
- Continue to Brush mow Healdville Rd.
- Mowed Cemeteries
- Filled pot holes on Pitcherville Rd. per resident request
- Continue to add hardpack long the edge of the new pavement on Hale Rd. Ext

**Wed.Sept.9, 2020**

- Finished applying the restorative maintenance application down on New Templeton Rd. and Hale Rd.
- Continue to Brush mow Healdville Rd. and started Old Westminster Rd.
- Cut up a tree on Healdville Rd.
- Swept Healdville Rd.

**Thurs.Sept.10, 2020**

- Chipped up tree branches on Healdville Rd. from the storm
- Continue to Brush mow Old Westminster Rd.
- Replaced blown hydraulic line on the 06 F450
- Replaced main broom on the sweeper
- Continue body work on the 95 GMC
- Replaced the broom on the Trackless

