Hubbardston DPW Bi-Weekly Log



July.31, 2022 - Aug.13, 2022

Mon.Aug.1, 2022

• Repaired a section of Burnshirt Rd. at the end of Thompson Rd.

Tues.Aug.2, 2022

- Rebuilt the catch basin on the corner of Brigham St. and Main St.
- Mowed Cemeteries
- Undercoated and installed fenders back on the excavator

Wed.Aug.3, 2022

- Mowed Cemeteries
- Removed old pavement on part of the Slade building parking lot for repair
- Continue to rust proof the 15 Freightliner
- Oil change and replace flex pipe on car#4 PD
- Looked at the light issue on the 94 GMC

Thurs.Aug.4, 2022

- Mowed common and Slade Building
- Oil change on car#3 PD
- Continue to rust proof the 15 Freightliner
- Replaced the horn on the 07 Backhoe
- Looked into the AC issue on the 05 excavator.

- Paved the Slade Building parking lot
- Removed a dead animal on New Westminster Rd.
- Continue to back the edge of the pavement on Kruse and Thompson Rd.

Mon.Aug.8, 2022

- Continue to rust proof the 15 Freightliner
- Continue to back the edge of the pavement on Kruse and Thompson Rd.
- Brush mowing Williamsville Rd. and Burnshirt Rd.
- Replaced blown hydraulic lines on the 15 Freightliner
- Check for a leaning branch at #21 Brigham St. per PD
- Met with DCR on Beaver issue on Brigham St.
- Mowed Cemeteries

Tues.Aug.9, 2022

- Air brake test
- Mowed Cemeteries
- Continue brush mowing Burnshirt Rd.
- Continue to back the edge of the pavement on Kruse and Thompson Rd.
- Installed a mirror at 177 Williamsville Rd.
- Put up road closed signs on Upper Intervale Rd. and removed the tree after Grid was done per PD
- Removed a dead animal on Williamsville Rd.

Wed.Aug.10, 2022

- Mowed Cemeteries
- Cleaned under guardrails on Burnshirt Rd.
- Continue brush mowing Burnshirt Rd.
- Lines painted on the new pavement at the Slade building and removed barriers

Thurs.Aug.11, 2022

- Continue to brush mow Burnshirt Rd.
- Finished cleaning under guardrails on Burnshirt Rd. and marked out basins
- Swept off the end of Morgan Rd. from stone debris per resident request
- Diagnose charging issue on the Cemetery mower
- Finished rust proofing the 15 Freightliner

	•	·	