


## Hubbardston DPW Bi-Weekly Log



Aug.14, 2022 – Aug.27, 2022

**Mon.Aug.15, 2022**

- Continue to brush mow Burnshirt Rd.
- Installed the spreader in the 12 Freightliner for the Preventative maintenance work on Burnshirt Rd., Williamsville Rd., New Westminster Rd. and Worcester Rd.

**Tues.Aug.16, 2022**

- Did a preventive maintenance on Burnshirt Rd. and part of Williamsville Rd.

**Wed.Aug.17, 2022**

- Mowed Cemeteries
- Repaired drainage on birches Rd. per resident request
- Brush mowing Mile Rd. per resident request
- Hot patched the school playground basin and Brigham St. basin that were rebuilt
- Fixed shifting issue with the brush mower
- Continue rust proofing the 09 Sterling

**Thurs.Aug.18, 2022**

- Mowed common and Slade Building
- Patched the mower deck on the brush mower
- Removed a dead animal at #5 Gardner Rd.

- Patched Pitcherville Rd.
- Continue rust proofing the 09 Sterling
- Brush mowing New Templeton Rd.

**Mon.Aug.22, 2022**

- Started sweeping Burnshirt Rd.
- Continue brush mowing New Templeton Rd.
- Replaced the drive motor and spinner motor on the Oshkosh
- Replaced a blown air can on Engine #2 FD
- Put old culvert pipe in the recycle dumpster

**Tues.Aug.23, 2022**

- Replaced blown rear air can on Engine#2 FD
- Continue brush mowing New Templeton Rd.
- Replaced a blown hydraulic pump on the brush mower
- Mowed Cemeteries
- Finished sweeping Burnshirt Rd.
- Put newer tires on Car #2 PD
- Installed spinner motor on the Oshkosh
- Continue to back the edge of the pavement on Thompson Rd.
- Added rip rap to sections of Thompson Rd.
- Removed a construction barrel from the river on Lombard Rd.

**Wed.Aug.24, 2022**

- Mowed Cemeteries
- Replaced the A/C pump on the excavator
- Started preventative maintenance on New Westminster Rd. from Prentiss Hill Rd. to Town line
- Continue rust proofing the 09 Sterling

**Thurs.Aug.25, 2022**

- Removed dead animals on New Templeton Rd. and Rt.62
- Continue preventative maintenance on New Westminster Rd. and Williamsville Rd.

- Brought the backhoe up to Hubb equipment to weld a plate on the bucket
- Continue rust proofing the 09 Sterling
-